THE BATTALION Page 8

FARMERS SURANCE GROUP

AUTO•FIRE•LIFE COMMERCIAL

RON ALLEN AGENCY 707 TEXAS AVENUE SUITE 110-A

696-9351

ST, FAIR, FRIENDLY SERVICE

National

Space shuttle to try again; launch set for Thursday

United Press International CAPE CANAVERAL, Fla. — The National Aeronautics and Space Administration has decided

The two hydraulic system engines that developed oil pressure trouble seconds before blastoff Wednesday will be fixed by draining contaminated gearbox oil, flushing the system and installing

new filters. 'Getting to a Thursday launch is a very tight schedule, but one which the mission management team feels can be made," a NASA

toff two days later, a delay of eight days from the first try.

power units was a compound produced by a chemical reaction between the oil, hydrazine fuel and a small amount of water normally

to try to re-launch the space shut-tle Columbia Thursday to see if a used spacecraft works as well as a new one. through two screens into the oil. The problem developed in two hydraulic pump engines that had not been serviced since the Columbia's first flight last April.

Horace Lamberth, chief of fluid systems at the Kennedy Space Center, said the problem showed that the auxiliary power units in the spaceship would have to be checked after each flight. Project officials had hoped to keep such

The Columbia is designed to







